

C.O.C.: ---

REPORT No. B21-34802

Report To:

MacLellan Water Technology
 388 Millhaven Rd., PO Box 392
 Odessa ON K0H 2H0 Canada

Attention: William Vander Wilp

Caduceon Environmental Laboratories

285 Dalton Ave
 Kingston Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

DATE RECEIVED: 23-Oct-21

JOB/PROJECT NO.: Jambo

DATE REPORTED: 27-Oct-21

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO.

Parameter	Total Coliform	E coli			
Units	cfu/100mL	cfu/100mL			
R.L.	1	1			
Reference Method	SM9222B	SM9222B			
Date Analyzed/Site	23-Oct-21/K	23-Oct-21/K			

Client I.D.	Sample I.D.	Date Collected				
Downstairs Bathroom	B21-34802-1	23-Oct-21	0	0		



R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an *

Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

Evan Livermore
 Supervisor/Microbiology

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from